






Assembly Instructions


1211-C







60 min








		1211-C
1	1	800x400x18MM
2	1	800x400x18MM
3	2	398x514x18MM
4	3	758x168x18MM
5A	3	332x100x18MM
5B	3	332x100x18MM
6	3	741x100x18MM
7	3	332x64x18MM
8	4	762x64x18MM
9	3	715x342x5MM
10	1	772x524x5MM





 φ 15x12 Ax28	 M6x35 Bx28	 φ 8x40 Cx16	 M3.5x15 Dx44
 350mm Ex6	 M6x24 Fx24	 70x70x20 Gx4	 Hx16
 φ38x190 Ix4	 Jx8	 φ 12x12 Kx24	 Lx3
 Mx3	 M6 Nx16	 φ 16xM6x1.5 Ox16	 5# Px1




1





$E = E1 + E2$


$M = M1 + M2$





2





3





4



5




6



7




Ax8




8



Ax4




9



10




Bx4





10-14

11




12





11-14

13




14





12-14

15





16



13-14

17



18

