







Assembly Instructions


9971







60 min







		9971
1	1	1200x400x18MM
2	1	1200x382x18MM
3A	1	382x264x18MM
3B	1	382x264x18MM
4	1	362x264x18MM
5	1	499x272x18MM
6	2	699x134x18MM
7A	2	332x80x18MM
7B	2	332x80x18MM
8	2	652x80x18MM
9	2	626x342x5MM
10	1	1172x274x5MM






 φ 15x12 AX12	 M6x35 BX12	 φ 8x40 CX12	 M3.5x15 DX53
 350mm EX4	 φ 12x12 FX16	 M6x24 GX16	 φ 16x1.5xM6 HX8
 M6x20 IX8	 JX3	 M4 KX6	 M5 LX1
 MX2	 NX1	 M6 OX8	





1




$E = E1 + E2$





2



3




4




5




AX6





6




7




8




9




10



11




12



X2

13




X2

14



FX8




X2

12-14

15



FX 8



X2


16



DX12



E1X4



X2

17

