








# Assembly Instruction





Panel No	Panel Sizes	Quantity
1	600*300*16	1
2	564*296*16	1
3	1284*298*16	1
4	1284*298*16	1
5	564*296*16	1

Panel No	Panel Sizes	Quantity
6	564*296*16	1
7	392*277*16	3
8	563*60*16	2
9	574*402*5	3




# Fittings




M6\*40

A=22



$\Phi 8*30$

B=36




$\Phi 15*12$

C=22




$\Phi 21$


D=28



F=1



E=12




Q=6





H=1


1




# 2




# 3





4





5



6



7



8

9

