











Assembly Instruction





Panel No	Panel Sizes	Quantity
1	1200*480*16	1
2	1200*480*16	1
3	98*478*16	1
4	98*478*16	1
5	98*442*16	1
6	579*94*16	1


Panel No	Panel Sizes	Quantity
7	579*94*16	1
8	1173*108*5	1
9	400*75*12	2
10	400*75*12	2
11	524*75*12	2
12	398*534*5	2




Fittings



A=6




B=12




C=6



D=28



E=6



F=1



M6*16

G1=16




M6*45

G2=2



H=1




J-3=2

J-4=1

J-2=2

J-1=2




N=2




O=16



P=16



Q=6



U=2



M3.5*12

V1=16




Z1=16












Z2=16


1




2




3




4



5




6




7


7-1



7-2




7-3




X2

8



9



10

