







Assembly Instructions


2106







60 min








2106

1	1	500*400*18MM
2	1	500*400*18MM
3	2	398*104*18MM
4	1	458*100*18MM
5A	1	350*80*15MM
5B	1	350*80*15MM
6	1	411*80*15MM
7	1	421*342*5MM
8	1	472*114*5MM






 $\phi 15*12$ AX8	 M6*35 BX8	 $\phi 8*40$ CX8	 M3.5*15 DX12
 FX1	 GX1	 HX4	 $\phi 38*405$ IX4
 M6*15 JX16	 350MM KX2	 $\phi 15*M6*1$ LX16	 M6 MX16
 M6*24 NX4	 $\phi 12*12$ OX4	 PX4	 QX4
 5# Rx1			





# 1




$$K=K1+K2$$




# 2



# 3




1X4





# 4




BX4




# 5




# 6



# 7



# 8




9-13

# 9




AX4



# 10




NX4





10-13

11




12



# 13



PX4





# 14





OX4



QX4



# 15



# 16

